

0020



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 11, 1988
1:30-3:00 p.m.

Permittee and/or Operators Name: Co-Op Mining Company
Business Address: P.O. Box 1245 Huntington, Utah 84528
Mine Name: Bear Canyon Permit Number: ACT/015/025
Type of Mining Activity: Underground ☒ Surface ☐ Other ☐
County: Emery State: Utah
Company Official(s): Ron Tucker
State Official(s): Bill Warmack and Bill Malencik
Partial: ☒ XX Complete: ☐ Date of Last Inspection: June 14, 1988
Weather Conditions: Clear and warm
Acreage: Permitted 900 Disturbed 10 Regraded Seeded Bonded 10
Enforcement Action: NOV 88-26-12-2

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	(X)	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION July 11, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Site conditions were dry; no major problems were noted with the exception of those stated herein. Other than the lump coal storage and mine water discharge, all other items are not a violation of UMC performance standards and/or the mining and reclamation plan.

1. PERMITS:

NOV 88-26-12-2 was issued for noncompliance with MRP - unauthorized coal storage and discharge of mine water from Hiawatha portal.

2. SIGNS AND MARKERS:

All signs and markers were up and in good repair.

4b. DIVERSIONS:

1. Culvert for undisturbed drainage at top storage yard has some slag in inlet area and should be cleared to prevent future problems.
2. Berming of upper storage pad needs to be completed by date stipulated in prior inspection report. There is some confusion on a) the storage pad as shown on the current surface facilities map and b) recent work on the storage pad. The mine official should submit a revised surface facilities map that would clarify the two items mentioned above and any other revisions by Sept. 6, 1988.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

Pond A is reaching full capacity for sediment. Pond needs to be cleaned out when dry and preferably before the high intensity storms hit this particular site.

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION July 11, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

4d. OTHER SEDIMENT CONTROL MEASURES:

Silt fence in undisturbed drainage ditch was up and functioning properly.

Copy of this Report:

Mailed to: Gerald Hansen, Co-Op Mining Co.

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: July 14, 1988